

MONUMENT RECORD

Corner I.D. #


N-11

STATE OF INDIANA - COUNTY OF MONROE

Section Fifteen (15), Township 10 North, Range 1 West

Monument Description & Remarks: Found Stone at NW Corner of NE 1/4 of
SW 1/4. Stone was 4" x 5" x 12", marked with "X", and leaning against post.
Corner witnessed 9/18/85.

Recovery Tie Drawing



State of Indiana
 County of Monroe

Space
 Reserved For
 Recording
 Officer

I, Michael W. Friley, County Surveyor, hereby certify
 that this document was prepared under my direction in
 accordance with the provisions of Section 17-3-64-4
 through 17-3-64-8 of the Indiana Code, being Acts of 1965,
 Chapter 319; and the above data is given under my hand and
 seal this 4th day of November, 19 93 A.D.

Indiana Registered Land Surveyor No. _____ or

Morgan-Monroe State Forest
 United States Government Agency

Darrell Breedlove, Timber Specialist
 Title

Field Book:

n/a

Page:

n/a

SECTION 15, T 10 N, R 1 W

On June 28, 1984, boundary line work in the section was begun as follows:

- A. -was shown where stone marker was originally located at SE corner of section by Hugh Gorman, 8595 Old 37 N, (adjoining landowner) who claims it had been removed 3-4 years prior to my visit by a surveyor working in SEC 23. A lath was observed east of the hole shown that was marked as SEC 23 corner. See Section 22, 1A + *10' below*
- B. -was shown where the NE corner SE $\frac{1}{4}$, SE $\frac{1}{4}$ is located--old fence wire and a fallen corner post substantiate that the location was correct.
- C. -a compass reference line was run south from a pipe found north of Chamber's Pike at the northeast section corner. At this point, exact measurements have not been made to the evidence found, but the hole where the stone supposedly sat is probably a better fit than the lath for the SE corner of SEC 15.
- D. -a large beech tree with wire pointing in three cardinal directions was found close to the reference line at NE corner of NE $\frac{1}{4}$, SE $\frac{1}{4}$.

Darrell Breedlove, Timber Specialist

2. Sept. 18, 1985

-lines painted in west half of section; signs posted at turning corners and $\frac{1}{4}$ - $\frac{1}{4}$ corners

-pin (set by Vollmer in 70's) found along Chamber's Pike at mid-NE $\frac{1}{4}$, NW $\frac{1}{4}$ indicates disagreement with fence found near ridge top. This fence surrounds a hay field and closes on mid-point of NW $\frac{1}{4}$.

-a hexagon marker (set by Vollmer-1985) also found along Chamber's Pike west of before mentioned pin. It's use is to establish north-easterly line along Chamber's Pike.

-two stones were witnessed at:

NW corner of NE $\frac{1}{4}$, SW $\frac{1}{4}$ (4" (w) x 5" (l) x 12" (h) with "X" leaning against post)

Azimuth (°)	257 <i>SW^{POW}</i>	140 <i>SW^{SEE}</i>	021
Species	SUM	SUM	SUM
DBH			
ob (in.)	13.2	20.9	16.9
Distance (ft.)	21.9	36.0	04.7

drawn 11-1-93

SE corner of NE $\frac{1}{4}$, SW $\frac{1}{4}$ (5" x 9" x 1" with "X")

Azimuth (°)	340	237	147
Species	REO	SUM	BIH
DBH			
ob (in.)	21.7	18.2	09.6
Distance (ft.)	06.7	45.3	13.9

-fence surrounds the biggest part of state ownership.

Darrell Breedlove
Darrell Breedlove, Timber Specialist